



300 W. Factory Road
Addison, IL 60101-5004
T:630-628-9999
F:630-628-9922

Email: sales@powervolt.com
Web Site: www.powervolt.com

For Immediate Announcement

Friday, July 28, 2017

Contact:

sales@powervolt.com

PowerVolt Announces Replacement Part Numbers for Discontinued Units Where Applicable

Powervolt has discontinued manufacturing certain part numbers and has identified replacement part numbers where applicable.

P/N	REPLACEMENT
AZE-100	CONSIDER CT SERIES
AZE-120	CONSIDER CT SERIES
AZE-150	CONSIDER CT SERIES
AZE-200	CONSIDER CT SERIES
AZE-250	CONSIDER CT SERIES
AZE-500	CONSIDER CT SERIES
AZOF-100	CONSIDER CT SERIES
AZOF-120	CONSIDER CT SERIES
AZOF-150	CONSIDER CT SERIES
AZOF-200	CONSIDER CT SERIES
AZOF-250	CONSIDER CT SERIES
AZOF-300	CONSIDER CT SERIES
AZOF-500	CONSIDER CT SERIES

P/N	REPLACEMENT
PV5401-1	BVU75FU5, BVU75FU6401-1
PV5201-1	STP-35XXX2.5
PV5201-2	STP-35XXX2.5 (switch selectable 120/240)
PV5202-1	STP-35XXX5
PV5202-2	STP-35XXX5 (switch selectable 120/240)
PV5301-1	STP-70ADC5 (switch selectable 120/240)
PV5301-2	STP-70ADC5 (switch selectable 120/240)
PV5302-1	Not exact match STP-70XXX5
PV5302-2	Not exact match STP-70XXX5(switch selectable 120/240)
PV5401-1	Not exact match STP-70XXX5(switch selectable 120/240)
PV5401-2	Not exact match STP-70XXX5(switch selectable 120/240)
PV5402-1	None
PV5402-2	None
PV5400M-1	None
BVS-030S10052	NO REPLACEMENT

P/N	REPLACEMENT
BVS-040S10052	NO REPLACEMENT
BVS-040S10051	NO REPLACEMENT
BVS-040S10122	NO REPLACEMENT
BVS-060S10121	NO REPLACEMENT
BVS-080S10121	NO REPLACEMENT
BVS-040S10242	NO REPLACEMENT
BVS-060S10241	NO REPLACEMENT
BVS-080S10241	NO REPLACEMENT
BVS-060M40001	NO REPLACEMENT
BVS-060M40011	NO REPLACEMENT
BVS-060M40021	NO REPLACEMENT
BVS-060M40031	NO REPLACEMENT
BVS-060M40041	NO REPLACEMENT
BVS-EGO1	NO REPLACEMENT
BVS-080M40001	NO REPLACEMENT
BVS-080M40011	NO REPLACEMENT
BVS-080M40021	NO REPLACEMENT
BVS-080M40031	NO REPLACEMENT
BVS-080M40041	NO REPLACEMENT
BVS-080M41001	NO REPLACEMENT
BVS-080M42001	NO REPLACEMENT
BVS-100EGO3	NO REPLACEMENT